

9/015/072

DOG-4  
9/20/96



A. Distance shot of Western Clay Company's access road and gypsum mine, notice UTU-73779 in T.24S., R.7E., Sections 14 and 23. 5-2-96.



B. Another distance shot of the access road and mine, Western Clay Company, notice UTU-73779 in T.24S., R.7E., Sections 14 and 23. 5-2-96.

9/015/072

DECH

9/20/96



C. Access road just west of the first realignment, Western Clay Company, notice UTU-73779 in T.24S., R.7E., Section 15. 5-2-96.



D. Looking west at the access road from the first realignment, Western Clay Company, notice UTU-73779 in T.24S., R.7E., Section 15. 5-2-96.

5/019/072

DOM  
9/20/96



E. Another view of the access road and mine as seen from the first realignment, Western Clay Company, notice UTU-73779 in T.24S., R.7E., Sections 14 and 23. 5-2-96.



F. Haul truck going east on the access road, Western Clay Company, notice UTU-73779 in T.24S., R.7E., Section 15. 5-2-96.

S/015/072

DOH  
5/20/96



G. Haul truck going down the access road just east of the first realignment, Western Clay Company, notice UTU-73779 in T.24S., R.7E., Section 15. 5-2-96.



H. Entrance to the gypsum mine, Western Clay Company, Notice UTU-73779 in T.24S., R.7E., Section 23. 5-2-96.

9/015/072

DOGM  
5/20/96



I. Southern gypsum stockpile, Western Clay Company, notice UTU-73779 in T.24S., R.7E., Section 23. 5-2-96.



J. Northern gypsum stockpile, Western Clay Company, notice UTU-73779 in T.24S., R.7E., Section 23. 5-2-96.

5/015/072

DOO4  
5/20/96



K. Overburden stockpile at the west end of the gypsum mine, Western Clay Company, notice UTU-73779 in T.24S., R.7E., Section 23. 5-2-96.



L. Loading at the northern stockpile, Western Clay Company, notice UTU-73779 in T.24S., R.7E., Section 23. 5-2-96.